AD

AD-E402 963

#### Technical Report ARCCD-TR-02003

# 120-mm TARGET PRACTICE CONE STABILIZED DISCARDING SABOT WITH TRACER (TPCSDS-T) M865 (E3) REWORK REPORT (POP-RIVET DESIGN)

Francis P. Donlon Brain A. Levine

October 2002



### U.S. ARMY ARMAMENT RESEARCH, DEVELOPMENT AND ENGINEERING CENTER

Close Combat and Armaments Center

Picatinny Arsenal, New Jersey

Approved for public release; distribution is unlimited.

20030228 159

The views, opinions, and/or findings contained in this report are those of the author(s) and should not be construed as an official Department of the Army position, policy, or decision, unless so designated by other documentation.

The citation in this report of the names of commercial firms or commercially available products or services does not constitute official endorsement by or approval of the U.S. Government.

Destroy this report when no longer needed by any method that will prevent disclosure of its contents or reconstruction of the document. Do not return to the originator.

#### REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-01-0188

The public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden to Department of Defense, Washington Headquarters Services Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.

PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.

						August and a second a second and a second an
	ctober 2002	YY)	2. REPORT TYPE Final			3. DATES COVERED (From – To)
4. TITLE AND S	UBTITLE				5a. C	ONTRACT NUMBER
120-mm Targ	get Practice (	Cone Stabil	ized Discarding Sa ork Report (Pop-Riv	bot with	5b. G	RANT NUMBER
macer (TFCC	3D3-1) W000	(LS) Newc	ork report (i op-raiv	ot Design)	5c. PF	ROGRAM ELEMENT NUMBER
6. AUTHORS				144400	5d. PF	ROJECT NUMBER
Francis P. Do	onlon and Bri	an A. Levir	ne		5e. TA	ASK NUMBER
					5f. W	ORK UNIT NUMBER
7. PERFORMIN	IG ORGANIZAT	ION NAME(S	S) AND ADDRESS(ES)	****		8. PERFORMING ORGANIZATION REPORT NUMBER
ARDEC, CCA Heavy Armar		(AMSTA-	AR-CCH-R)			e e
Picatinny Ars	enal, NJ 078	306-5000				40 000 HOO DE HOO HET OFFICE A OFFICE HOO
9. SPONSORIN ARDEC, WE		G AGENCY I	NAMES(S) AND ADDRI	ESS(ES)		10. SPONSOR/MONITOR'S ACRONYM(S) TACOM/ARDEC
Information F Picatinny Ars			A-AR-WEL-TL)			11. SPONSOR/MONITOR'S REPORT NUMBER(S)
12. DISTRIBUT			IENT			Technical Report ARCCD-TR-02003
Approved for	public releas	se; distribut	tion is unlimited.			, it
13. SUPPLEME	NTARY NOTES	5				
was adopted a together to inv disassembling with three differ the number on others becaus around the circuscenario provide reworked a	99, a major red and put into the restigate the properties of the erent solutions are choice of the e of its low made cumference of ded adequate and reissued to	e field for test oblem. The insuring che for field fix is team, but aintenance at the case ac axial suppo	sting. A few months I a primary focus of the emical compatibility, a rework: (a) pop rivets the pop rivets had lower and symmetry. The dapter. The pop-rivet ort, while passing all o	ater, reports group was the and meeting (b) foam fill ver overall ri esign consist design was p	of failu to reinfo all ballid I, and (co sk. The sted of 1 put throu	was undertaken. A snap-joint method re were reported and a team was brought orce the joint configuration without stic requirements. The team came up c) pool of epoxy. The foam design was e pop-rivet design was chosen over the 5 countersunk pop rivets equally spaced ugh the entire screening process and the sting. Suspended cartridges could now
15. SUBJECT T		cartridge				
16. SECURITY	CLASSIFICATI	ON OF:	17. LIMITATION ABSTRACT	OF 18. NU	JMBER	19a. NAME OF RESPONSIBE PERSON Francis Donlon and Brian Levine
a. REPORT   t	o. ABSTRACT U	c. THIS PA			GES 29	19b. TELEPHONE NUMBER (Include area code) (973) 724-6709/6720
		J				Standard Form 208 (Pay 8/08)

### CONTENTS

		Pag
Intro	oduction/Background	•
Field	d Fix Rework	.•
	General Plastic Countersunk Screw Design Plastic Countersunk Pop Rivet Design Foam Fill Design Pool of Epoxy Design Demonstration Test Verification Tests Additional Screening Pendulum Test Pendulum Test Description User Loading Test Qualification Testing	
Con	clusion	6
Dist	ribution List	25
	FIGURES	·
1	Green epoxy residue with adapter material attached	7
2	Eighteen setscrews design	7
3	Eighteen pop rivets design	8
4	Plastic pop-rivet design	8
5	Case adapter and insert cover interface with setscrews	
6	Case adapter and insert cover interface for pop rivets	
7	Positioning and drilling fixture (pop-rivet design)	10
8	Modification to pop-rivet schematic	10
9	Modification to pop rivet	11
10	Foam fill design	11
11	Foam fill design (rear view)	12

## FIGURES (continued)

		Page
12	Pool of epoxy design	12
13	Pendulum test	13
14	Pendulum test in operation	14
15	Pendulum test setup	15
16	Pendulum test setup (2)	15
17	Pendulum test failure	16
18	Rapid fire residue test for pop-rivet design (from tank)	17
19	Stationary users tests	18
20	Nitride coated drill and countersinking tool	20
21	120-mm TPCSDS-T M865E3 with pop-rivet fix	20
	TABLES	
1	M865E3 pop rivet secured cargo vibration test: summary of dispersion, velocity, and pressure data – 03 December	21
2	M865E3 pop rivet secured cargo vibration test: summary of dispersion, velocity, and pressure data – 04 December	21
3	M865E3 pop rivet sequential rough handling and secured cargo vibration tests: summary of dispersion, velocity, and pressure data – 05 December	22
4	M865E3 pop rivet sequential rough handling and secured cargo vibration test: summary of dispersion, velocity, and pressure data – 06 December	22
5	M865E3 pop rivet sequential rough handling test: summary of dispersion, velocity,	23

#### INTRODUCTION/BACKGROUND

Production of the 120-mm M865 target practice cone stabilized discarding sabot with tracer (TPCSDS-T) began in 1985 using the "bolt on cover" (BOC) design that was taken directly from the Rheinmetall technical data package (TDP). In 1988, per Department of the Army (DA) direction, 25,000 M865's were procured from each of the prime contractors using a "Form, Fit and Function Specification." Alliant Tech Systems (ATK) introduced the "glue on cover" (GOC) on their 25,000 quantity. Subsequently, because of the excellent performance of those rounds and the substantial cost savings, the GOC was included as an alternate in the government TDP. General Dynamics Ordnance and Tactical Systems (GD-ODTS) formally Primex Technologies Inc., also chose to adopt the GOC, but began to experience target impact dispersion (TID) problems that they believed were directly attributable to the GOC design and they chose to return to the BOC. Subsequently, with the transition of ATK's M865 projectile production from Valentec to Ferrulmatic, ATK also began to experience TID problems, and by 1995 both prime contractors had returned to the BOC design.

In 1998-1999, a major redesign of the M865 adapter and insert cover interface was implemented along with a change in the cartridge case paint system from polyurethane to epoxy. The snap-joint attachment method was similar to that used on the 120-mm M829 and M829A1 armor piercing fin stabilized discarding sabot with tracer (APFSDS-T) kinetic energy (KE) tactical rounds, and the change in paint system reflected a change made to all tactical rounds several years earlier to improve handling durability. The cartridges were subjected to and passed product qualification tests including sequential rough handling (ITOP 4-2-602, page 9) and sequential vibration (secure cargo and rack) tests (ITOP 1-2-601 Sec. B and C). Shortly after release of these new rounds (April 1999), field problems were encountered with separation of the projectile from the cartridge case at the snap joint.

By May 2000, a modification consisting of a longer nylon insert and approximately 24 g of green epoxy was introduced to provide a more durable projectile to cartridge case attachment. Initial field experience with the modified rounds in October 2000, indicated that the joint strength issue was resolved, but there had been a number of instances of chambering failures due to large pieces of adapter bonded to green epoxy (fig. 1) adhering to an epoxy paint coating in the forward area of the cannon chamber, called chamberage. The residue issue was serious enough to warrant establishing a team to investigate the problem. By June 2001, a modification consisting of half the amount of epoxy (approximately 12 g of green epoxy) was introduced to still provide a durable projectile to cartridge case attachment, which also eliminated the residue in the gun tube issue. After a thorough investigation by the team, a report was issued titled "Report of Barrel Residue Investigation Team," dated January 25, 2002.

#### **FIELD FIX REWORK**

Approximately 140,000 rounds of the original snap-joint design were suspended from use, most where in storage at Iowa Army Ammunition Plant (IAAP), but approximately 42,000 where in storage in forts in Germany and the United States. The field fix rework procedure had to encompass a design that would reinforce the original case adapter/insert cover joint configura-tion. The design would increase the axial strength beyond that currently provided by the adapter lip material without the need for disassembly of the cartridge, while allowing for complete chamberability, insuring component chemical compatibility with propellant and meeting ballistic residue requirements.

#### General

On 16 November 2001, a brainstorming session was conducted with U.S. Army Armament Research, Development and Engineering Center (ARDEC) and Program Manager-Tank and Medium-caliber Armament systems (PM-TMAS) personnel with representatives from ATK and GD-ODTS connected by telephone. Many of the ideas generated in that session carried over into the session held on 05 December (reference report RN-001222-001 titled "M865 Field Fix Rework and Interim Residue Fix Brainstorming Session," dated 22 December 2001). The team concluded the following three concepts should be pursued for the field fix rework.

- Pop rivets
- Foam fill
- Pool of epoxy

The foam design was the number one choice of the brainstorming team; however, the pop rivets had a lower overall risk because of supporting test data.

During the demonstration phase of the program three types of mechanical rework fixes were simultaneously tested along with the foam fill and pool of adhesive designs. The three mechanical designs were 18 plastic countersunk screws (fig. 2), 18 plastic countersunk pop rivets (fig. 3), and 15 plastic countersunk pop rivets (fig. 4). The 15 pop-rivet design was initiated after the 18 plastic rivets and screws designs were initially tested with excellent results. This 15 pop-rivet design was chosen because of economic (less rivets and machining) and symmetry (less chance of the rivets to interfere with the slots on the insert cover) attributes.

#### **Plastic Countersunk Screw Design**

This design was pursued by GD-ODTS and reinforced the existing joint by inserting a series of nylon screws through the case adapter/insert cover interface equally spacing each fastener around the cartridge circumference (fig. 2). This required the drilling, tapping, and counter-sinking of the case adapter and insert cover interface (fig.5) to a controlled depth then applying epoxy into each hole prior to inserting nylon countersunk screws for a below flush installation. The tapping operation was labor-intensive requiring additional fixtures and not very cost effective.

#### Plastic Countersunk Pop Rivet Design

This design reinforced the existing joint by inserting a series of nylon pop rivets through the case adapter/insert cover interface equally spacing each fastener around the cartridge circumference (fig. 4). This required the drilling and countersinking of the case adapter and insert cover interface (fig.6) to a controlled depth then installing modified pop rivets. The design required a drill fixture to consistently position the holes in their exact location (fig. 7). The modification to the pop rivet (figs. 8 and 9) consisted of machining the head to allow for countersinking and a below flush installation. The modification to the pop rivet was less costly when compared to the tapping operation of countersunk screw design.

#### Foam Fill Design

This design was initiated by ATK and pursued by ARDEC requiring the drilling of a hole in the case adapter and injecting urethane foam into the ullage area between the case adapter and slotted conical fin to stabilize the projectile. The design provided the projectile with additional support in fin area (fig. 10). This design seemed to provide a solution to the problem, but encountered large negative delta pressures, which could not be resolved (fig. 11). To insure the negative delta pressures were inherent of the foam fill design, 36 rounds were modified to test the foam fix concept.

Twelve rounds were modified using the original foaming method. Foam was injected into the loaded cartridges through the pressure port in the adapter until all the ullage appeared to be filled. The hole was then taped over using duct tape.

Twelve rounds were modified using a "pre-cured" foaming method. The propellant was downloaded and the cartridge cases were separated from the adapters. The propellant for each round was put into a separate bag and marked so that each round would have the same charge weight that it started with. Each adapter was filled with a 1-in. layer of foam. After curing for 24 hrs, new cartridge cases were glued to the adapters. The rounds were chambered tested to check for proper alignment. After allowing the foam to cure for another 12 hrs, the propellant was loaded back into the rounds.

Twelve rounds were modified using a "new and improved" technique developed at IAAP by ATK, GD-ODTS, and ARDEC. The process used was:

- Drill three holes 9/16 in. in diameter, 120 deg apart, 7/8-in. down from the top of the adapter
  - Hand shake round to level the propellant bed
  - Push the propellant bag down with a dowel rod through all three holes
  - Tape each hole with 1 to 2 layers of masking tape
  - Poke through tape on one hole with small dowel rod
- Insert foam can straw through hole in tape, place straw to the right of the core and as far back as possible
  - Fill right side with foam for 5 sec, while pulling straw back towards hole

#### **Pool of Epoxy Design**

This design required the drilling of a hole in the case adapter and inverting the cartridge (nose down) during epoxy installation. The epoxy used was a two-part epoxy consisting of Epon 828 and Versamid 140. The epoxy was pooled on the rear of the sabot and onto the adapter. In addition, a method had to be developed to keep the propellant bag out of the way during epoxy installation (fig. 12). The design contained additional concerns. Since there was an existing problem with epoxy residue on the current production design, this design, although pursued, was not adopted.

#### **Demonstration Test**

A demonstration test of the three designs: foam, plastic pop-rivet, and pool of epoxy (fig. 12) was successfully completed at Aberdeen Proving Ground (APG). Ten rounds each were subjected to a TID ballistic test at ambient temperature.

#### **Verification Testing**

Two designs, foam and pop rivet, were selected for verification testing at APG. The pool of epoxy design was eliminated due to production and residue concerns. Thirty rounds each were unsuccessfully subjected to a ballistic test at ambient, hot, and cold temperatures. An additional 20 rounds each were successfully subjected to transportation vibration, rough handling, and drop testing. The plastic pop rivet and the foam design failed the TID requirement at cold and negative delta pressure requirement at hot, respectively. The TID problem may have been a test anomaly because a similar problem was encountered with the control rounds. The control rounds were from the same lot previously used when preliminary testing for the pop-rivet design was conducted. The negative delta pressure problem was real; additional testing confirmed it.

The team initiated a go forwarded plan, which was approved by the Integration Team. The plan proposed was three fold. First, redo the TID test for the pop-rivet design. The test rounds would be shot alternating with the control rounds. Second, investigate and understand the negative delta pressure problem and modify the design and/or conduct additional ballistic testing to determine the extent of the problem.

Although many methods were used to install the foam verification tests indicated the foam design still had large negative delta pressures while the pop rivet design pressures were acceptable. Since the negative delta pressure issue could not be resolved the foam design was terminated and all effort was put into the pop rivet design.

#### **Additional Screening**

As part of the verification test, an additional screening was conducted. The screening consisted of rough handling and chambering/extraction tests in a M1A2 tank located at ARDEC. Basically, the cartridge was knocked about while loading and extracting five times in the process of checking for damage each time.

#### **Pendulum Test**

The pendulum test (fig. 13) was developed early on during the field fix rework program to provide a good initial screen for a design's level of robustness and anticipated performance during the user-loading test. The pendulum test is intended to simulate a side impact of the cartridge with an object and places a dynamic bending load on the projectile/adapter interface (fig. 14). This test depicts a worst-case scenario of what can happen to a cartridge when being handled within the turret of the tank.

#### **Pendulum Test Description**

The pendulum test provides a controllable side impact to the front of a projectile simulating dropping the front of the round on the breechblock during chambering or otherwise hitting the projectile during unpackaged handling. The pendulum test impact point is 3.75 in. from the tip of the core (fig. 15) and the distance from the pivot point to the tip of the core is 77 in. (fig. 15). The cartridge is suspended upside down by the case base then pulled back and released to impact a steel angle iron on a wall (fig. 16). The distance of the swing is measured diagonally from the wall intended impact to the core intended impact. The test consists of a series of swings starting at 2 ft then going to 3 ft, 4 ft, etc. (fig. 16). The test is stopped when the joint separates (fig. 17) to a point where it does not look like it chambers or the sabots become loose. The test is never conducted beyond 6 ft. The design that came apart in the field had only taken 3 ft to separate the case adapter from the insert cover not allowing the projectile to chamber.

#### **User Loading Test**

As part of the verification and qualification tests, the pop rivet and foam design cartridges were subjected to a user-loading test. The test was conducted at APG and consisted of Master Gunners rough handling, while loading and chambering/extracting the cartridges. The Master Gunner's would deliberately try to handle the round in a manner they would expect a very rough loader to do. The intent is not to see how hard they can bang the round, but rather expose the round to banging that it would expect to see in the field. Although the test was very subjective, it was a recommendation of what was acceptable for the M865E3 pop-rivet design.

#### **Qualification Testing**

Qualification testing for the M865E3 pop-rivet design was conducted at APG and consisted of sequential rough handling (SRH) tests and secured cargo vibration (SCV) tests with temperature conditioning. In addition, chamber and extraction tests, user-loading tests, and residue tests had to be conducted as part of the qualification testing. The SRH and SCV tests were conducted on the 3<sup>rd</sup> through the 7<sup>th</sup> of December 2001. The control rounds used were BOC as well as unmodified M865 cartridges. Summaries of dispersion, velocity, and pressure results are presented in tables 1 through 5.

As part of the user-loading test, a stationary users test (tank not moving) was conducted in which 15 rounds from all four designs were tested simultaneously. Two of the designs, optimum epoxy and reduced epoxy humiseal adapter, were part of the residue test. The other two designs, pop rivet and expanding foam were part of the field fix rework test. Two of the designs, foam and reduced epoxy/humiseal showed anomalies. The results were shown in figure 19.

The "rapid fire" residue test (fig.18) was designed by the Residue Team and conducted at APG during the March 2001 timeframe. The tests indicated residue was not an issue for the pop-rivet design.

The M865E3 pop-rivet design met all the requirements of the qualification tests with acceptable results.

#### CONCLUSION

Many of the designs recommended by the Brainstorming Team had merit, but the pop-rivet design proved to be the best scenario. The field fixing of the M865E3 target practice cone stabilized discarding sabot with tracer cartridges (fig. 21) by adding 15 nylon countersunk pop-rivets equally spaced around the circumference of the case adapter provided the projectile with adequate support to pass all qualification testing. This allowed the suspended cartridges at lowa Army Ammunition Plant (IAAP) to be reworked and then reissued to the stockpile. The field modification to the existing cartridges could be accomplished without downloading or destroying any of the existing assets. Fixtures (fig. 7) and tooling (fig. 20) to facilitate the field modifications were developed by the U.S. Army Armament Research, Development and Engineering Center (ARDEC) and supplied to the contractor (IAAP) for implementation. The modified pop rivets (countersinking operation) were designed by ARDEC. ARDEC also developed a process to mold the pop rivets to final dimensions without any additional machining, therefore reducing costs. ARDEC is also supplying the pop rivets to IAAP.




Figure 1
Green epoxy residue with adapter material attached




Figure 2
Eighteen setscrew design




Figure 3
Eighteen pop-rivet design





Figure 4
Plastic pop-rivet design



PROJECT STATUS: 31 OCT 2000 R.K. BERSCH

Figure 5
Case adapter and insert cover interface with setscrews




Figure 6
Case adapter and insert cover interface for pop rivets




Figure 7
Positioning and drilling fixture (pop-rivet design)




Figure 8 Modification to pop rivet schematic




Figure 9 Modification to pop rivet




Figure 10 Foam fill design




Figure 11 Foam fill design (rear view)




Figure 12 Pool of epoxy design




Figure 13 Pendulum test




Figure 14 Pendulum test in operation






Figure 15 Pendulum test setup




Figure 16 Pendulum test setup (2)




Figure 17 Pendulum test failure

DATE	LOT	MODIFICATION/FIX	N	AMMOTEMP	TUBE	Rapid Fire?	RESULTS
12 Dec 00	ORI00H703-002A	No Mod	10	20 F (-7 C)	1146	No	No Residue
12-13 Dec 00	ORI00H703-002A	No Mod	10	-50 F (-46 C)	1146	No	No Residue
13 Dec 00		No Mod	10	145 F (63 C)	1146	No	No Residue
13 Dec 00	ORI00H703-002A	Double-sided adhesive on adapter	10	20 F (-7 C)	1146	No	No Residue
13 Dec 00	ORI00H703-002A	Double-sided adhesive on adapter	10	-50 F (-46 C)	1146	No	No Residue
13 Dec 00	ORI00H703-002A	Double-sided adhesive on adapter	10	145 F (63 C)	1146	. No	No Residue
13 Dec 00	ORI00H703-002A		9	20 F (-7 C)	1146	Yes	10th Rd stuck
8 Jan 01	ORI00H703-002A		9	20 F (-7 C)	1146	Yes	No Residue
16 Jan 01	OR100H703-002A		87	20 F (-7 C)	1146	Yes	No Residue
16 Jan 01	OR100H703-002A		39	125 F (52 C)	1146	Yes	No Residue
16 Jan 01	OR100H703-002A		13	-25 F (-32 C)	1146	Yes	No Residue
17 Jan 01	OR100H703-002A		83	-25 F (-32 C)	1146	Yes	No Residue
17 Jan 01	OR100H703-002A		45	125 F (52 C)	1146	Yes	No Residue
18 Jan 01	OR100H703-002A		18	20 F (-7 C)	1146	Yes	No Residue
18 Jan 01		No Mod	9	125 F (52 C)	1146	Yes	No Residue
24 Jan 01		Teflon Tape Single Layer	5	70 F (21 C)	1146	Yes	No Residue
13 Mar 01		No Mod (Remote Firing for Safety)	3	32 F (0 C)	6385	Yes	No Residue
13 Mar 01		No Mod (Temperature Inst Test)	3	32 F (0 C)	6385	Yes	4th Rd stuck
13 Mar 01		No Mod (Temperature Inst Test)	8	32 F (0 C)	6385	Yes	No Residue
13 Mar 01	ORI00H703-002A	No Mod (Controls)	7	32 F (0 C)	6385	Yes	No Residue
13 Mar 01	ORI00H703-002A	No Mod (Controls)	4	32 F (0 C)	6385	Yes	5th Rd stuck
13 Mar 01	ORI00H703-002A	No Mod (Controls)	2	32 F (0 C)	6385	Yes	3rd Rd stuck
14 Mar 01	ORI01B125-001	Gray Epoxy & New Gen Insert "Fix"	8	32 F (0 C)	6385	Yes	9th Rd stuck
14 Mar 01	ORI01B703-005	Humiseal Paint & Less Epoxy "Fix"	12	32 F (0 C)	6385	Yes	13th Rd stuck
15 Mar 01	ORI01B001S270	New Gen Insert & Less Green Epoxy "Fix"	15	32 F (0 C)	6385	Yes	No Residue
15 Mar 01	ORI01B001S270	New Gen Insert & Less Green Epoxy "Fix"	15	32 F (0 C)	6385	Yes	No Residue
15 Mar 01	ORI01B001S269	New Gen Insert Only "Fix"	9	32 F (0 C)	6385	Yes	10th Rd stuck
15 Mar 01	ORI99G701-001B	Pop Rivet Design	15	32 F (0 C)	6385	Yes	No Residue
15 Mar 01	ORI99G701-001B	Pop Rivet Design	15	32 F (0 C)	6385	Yes	No Residue
16 Mar 01	ORI010001S271	Nylon Wedge Ring Design "Fix"	15	32 F (0 C)	6385	Yes	No Residue
16 Mar 01	ORI010001S271	Nylon Wedge Ring Design "Fix"	15	32 F (0 C)	6385	Yes	No Residue
16 Mar 01	ORI00H703-002A	No Mod (Controls)	4	32 F (0 C)	6385	Yes	5th Rd stuck
16 Mar 01	ORI010001S271	Nylon Wedge Ring Design "Fix"	10	32 F (0 C)	6385	Yes	No Residue
20 Mar 01	ORI99G701-001B	Pop Rivet Design	15	32 F (0 C)	6385	Yes	No Residue
20 Mar 01	ORI99G701-001B	Pop Rivet Design	5	32 F (0 C)	6385	Yes	No Residue
20 Mar 01	ORI01B001S270	New Gen Insert & Less Green Epoxy "Fix"	15		6385	Yes	No Residue
20 Mar 01	ORI01B001S270	New Gen Insert & Less Green Epoxy "Fix"	5	32 F (0 C)	6385	Yes	No Residue
20 Mar 01		Controls with Triple Teflon Tape on Adapter	10		6385	Yes	No Residue
20 Mar 01	OR100H703-002A	No Mod (Controls)	15		6385	Yes	No Residue
20 Mar 01	OR100H703-002A	No Mod (Controls)	4		6385	Yes	5th Rd stuck
29 Mar 01	OR199B700-001B	Bolt-on Cover Design with Epoxy Paint	15		6385	No	No Residue
29 Mar 01	OR199B700-001B	Bolt-on Cover Design with Epoxy Paint	11	32F (0C)	6385	No	12th Rd stuck
29 Mar 01	OR199B700-001B	Bolt-on Cover Design with Epoxy Paint	15	32F (0C)	6385	No	No Residue
29 Mar 01	ORI99B700-001B	Bolt-on Cover Design with Epoxy Paint	4	32F (0C)	6385	No	No Residue

Figure 18
Rapid fire residue test for pop-rivet design (from tank)

STATIONARY USER TEST WITH M865 (4 MODS) AT APG 3/7/2001

				TANK	HATCHES	
LOT	DESIGN	LOADER	EVENT	тс	Loader	ANOMALIES/NOTES
125-001	Optimum Epoxy	SSG Baker	3 Power Loads (1 rd)	Closed	Open	
	New IC	SFC Gross	3 Power Loads (1 rd)	Closed	Open	
		SSG Miller	3 Power Loads (1 rd)	Closed	Open	
		SSG Miller	"Bend" removing from Ready Rack	Closed	Open	
			Bang Tip on Strut Support			
			Bang Cartridge/Projectile on Breech			
			Bang Projectile on Loader's Tray			
		SSG Baker	"Bend" removing from Ready Rack	Closed	Open	
		4	Bang Tip on Strut Support			
			Bang Cartridge/Projectile on Breech			
			Bang Projectile on Loader's Tray			
		SFC Gross	"Bend" removing from Ready Rack	Closed	Open	
			Bang Tip on Strut Support			
			Bang Cartridge/Projectile on Breech			
			Bang Projectile on Loader's Tray			
701-1B	Pop Rivet Fix	SSG Baker	3 Power Loads (1 rd)	Closed	Open	
		SFC Gross	3 Power Loads (1 rd)	Closed	Open	
		SSG Miller	3 Power Loads (1 rd)	Closed	Open	
		SSG Miller	"Bend" removing from Ready Rack	Closed Closed	Open	
			Bang Tip on Strut Support		-	
			Bang Cartridge/Projectile on Breech			
			Bang Projectile on Loader's Tray			
		SSG Baker	"Bend" removing from Ready Rack	Closed	Open	
			Bang Tip on Strut Support			
			Bang Cartridge/Projectile on Breech			
			Bang Projectile on Loader's Tray			
		SFC Gross	"Bend" removing from Ready Rack	Closed	Open	MOPP Mask Worn by Loader
			Bang Tip on Strut Support			MOPP Mask Worn by Loader
			Bang Cartridge/Projectile on Breech			MOPP Mask Worn by Loader
			Bang Projectile on Loader's Tray			MOPP Mask Worn by Loader

Figure 19 Stationary users test

### **CLAIMS NOT INCLUDED**

PAGES 19 - 20

Table 1 M865E3 pop rivet secured cargo vibration test: summary of dispersion, velocity, and pressure data – 03 December

						Bore	sight & w	Boresight & wind corrected	ted		(sdu) ajzznjy	(sdw)	Mea	Mean falloff velocity (m/s)	elocity (n	u/s)	Cha	mber pre	Chamber pressure (bars)	irs)	Mean
	Test		Cond.		Targe	arget impact dispersion, mils	ispersion	, mils	DOF	ī								•			T4
-	round	Round	Temp			1000 m	2500 m	E	2500 m	E			-0	1000-	2000-	5	Rear	- Leo	Forward	ard	time
	number	type	<b>်</b>	z	Hor	Ver	Hor	Ver	Hor	Ver	Mean	SD	1000	2500	3000	avg	Mean	SD	Mean	SD	(ms)
-	1-3	Spotter	-32	က	0.58	0.38	0.46	0.38			1618.2	29.84	307.5	319.5	0	313.5	4408	88.6	4149	103.4	24
	4-8	Control	-32	S	0.37	0.34	0.36	0.35			1637.5	3.37	327.9	319.5	0	323.7	4380	41.6	4183	31.8	22
3 Dec	9-10	Spotter	-32	2	0.22	0.48	0.09	0.55			1633.1	16.26	318.8	318.3	0	318.5	4456	62.9	4226	5.0	21
3 Dec	11-15	scv	-32	5	0.23	0.23	0.27	0.26			1614.1	4.77	329.6	316.4	0	323.0	4110	23.2	3925	27.5	32
3 Dec	16-20	scv	-32	5	0.24	0.36	0.23	0.36			1610.5	3.74	327.8	316.8	o	322.3	4075	4.4	3899	37.7	56
3 Dec	21-25	Control	-32	5	0.38	0.42	0.29	0.44			1642.4	5.96	325.7	318.7	0	322.2	4378	49.7	4203	39.0	21
-		Pooled test	st	15	0.21	0.28	0.24	0.30			1612.2	5.31	329.7	316.5	0	323.1	4077	51.7	3897	46.7	28
		DOF applied	led				020	900							-						

Table 2 M865E3 pop rivet secured cargo vibration test: summary of dispersion, velocity, and pressure data – 04 December

						Bore	Baresight & wind corrected	ind corre	cted		Muzzle (mps)	(sdw)	Mea	Mean falloff velocity (m/s)	elocity (n	(S/L	Cha	mber pre	Chamber pressure (bars)	ĵ	Mean
Date	Test		Cond		Target ir	t impact o	mpact dispersion, mils	, mils	8	ų.											74
Fired	round	Round	Temp		100	1000 m	2500 m	EC	2500 m	Ε			-0	1000-	2000-	6	Rear	ž	Forward	ard	time
2001	number	type	ဉ်	z	Hor	Ver	Hor	Ver	Hor	Ver	Mean	SD	1000	2500	3000	avg	Mean	SD	Mean	SD	(SILL)
														4					-		
t Dec	31-35	Control	25	5	0.15	0.29	0.14	0.28			1726.8	4.18	334.4	322.4	0	328.4	5072	71.7	4944	81.3	13
1 Dec	36-40	SCV	52	S	0.09	0.20	90.0	0.23			1724.2	5.11	335.9	322.2	0	329.0	4906	28.2	4752	29.8	12
t Dec	41-44	scv	52	4	0.20	60.0	0.22	0.09			1721.3	1,67	332.7	320.7	0	326.7	4907	24.7	4742	22.8	13
		Pooled test	set	on	0,14	0.16	0.15	0.18			1722.9	4.01	334.5	321.5	0	328.0	4906	26.8	4748	27.0	12
		DOF applied	lied				0.13	0.16							Control of the last of the las						

Table 3
M865E3 pop rivet sequential rough handling and secured cargo vibration tests: summary of dispersion, velocity, and pressure data – 05 December

						Bore	Boresight & wind corrected	vind corre	cted		Muzzle	Muzzle (mps)	Me	Mean falloff velocity (m/s)	velocity (	(S/LL	S	mber nre	Chamber pressure (bars)	(8)	Mean
	ist L		Cond		Targe	irget impact dispersion, mils	dispersion	a, mils	ă	DOF	1					•				`	4
Fired	DOUG.	Round	Temp		100	1000 m	250	2500 m	250	2500 m	1		0-0	1000	2000	5	å	Rear	Forward	p.e/	tine
_	number	type	ဉ	z	Hor	Ver	Hor	Ver	Hor	Ver	Mean	SD	1000	2500	3000	Ď∧B	Mean	SD	Mean	SD	(SILL)
5 Dec	45-49	Control	52	S	0.31	0.23	0.27	0.27			1721.3	4.39	333.1	3218	c	377.4	5072	34.8	ARRO	427	13
5 Dec	50-55	scv	52	9	0.21	0.10	0.19	0.14			1720.8		332.5	321.3	0	3269	4928	35.7	4743	38.7	5
5 Dec	26-60	scv	25	2	0.03	0.14	0.05	0.16			1735.3	2.72	331.7	321.0	0	3263	5095	38.8	4973	34.3	2
5 Dec	61-65	scv	25	5	0.18	0.15	0.14	0.15			1734.8	0.90	329.9	320.8	0	325.3	5111	32.3	4948	42.5	=
2 Dec	66-71	scv	25	S	0.22	0.15	20.0	0.25			1739.1	4.64	333.2	319.5	0	326.4	5115	646	4943	888	000
		Pooled test	st	21	0.18	0.13	0.13	0.18			1731.4	3.03	331.9	320.7	0	3263	9505	44.2	4882	47.5	=
٦		DOF applied	fed				0.11	0.18													:
														•							
2 Dec	72-81	SRH	52	S	0.11	0.10	0.18	0.11			1730.1	5.14	328.5	317.3	0	324.8	5066	48.6	4870	52.0	12
5 Dec	77-81	SRH	52	5	0.17	0.03	0.08	0.03			1731.5	3.66	328 1	317.5	0	3228	5065	203	487B	104	2
5 Dec	82-86	SRH	52	5	0.03	0.15	0.11	0.17			1733.9	1.89	330.0	318.5	0	3242	5077	33.5	4878	37.5	10
7		Pooled test	st	15	0.12	0.10	0.13	0.12			1731.8	3.81	328.9	317.8	0	323.9	5069	36.4	4875	37.5	12
		DOF applied	lied				0.11	0.10												;	
						*								1	1			-	-	_	

M865E3 pop rivet sequential rough handling and secured cargo vibration tests: summary of dispersion, velocity, and pressure data – 06 December

	,					Bore	Boresight & wind corrected	ind corre	cted		Muzzle (mps)	(mps)	Me	Mean falloff velocity (m/s)	velocity (1	1/8)	Cha	mber pre	Chamber pressure (bars)	irs)	Mean
	est		So a		Targe	irget impact dispersion, mils	lispersion	mils '	DOF	JF											7
Fred	Lound	Round	emb		100	1000 m	2500 m	E	250	2500 m			-0	1000	2000-	5	Rear	-	Forward	'srd	fine emi
	number	Abe	ပ္	z	Hor	\ \	Hor	Ver	Hor	Ver	Mean	SD	000	2500	3000	BVG	Mean	SD	Mean	SO	(ms)
1																-					
6 Dec	87-91	Control	25	2	0.15	0.25	0.16	0.26			1721.5	5.81	328.0	3183	0	323 1	5089	75.2	4895	65.2	5
6 Dec	95-96	SRH	52	2	0.20	0.15	0.16	0.13			1728.0	3.34	327.0	317.1	0	322.1	5078	30.4	4874	35.3	2
6 Dec	97-101	SRH	52	5	0.09	0.18	0.10	0.17			1727.6	4.14	326.8	316.9	0	321.8	5020	23.6	4819	413	12
9090	102-106	SRH	25	2	0.12	0.10	0.11	90.0			1727.7	5.44	325.8	317.1	0	321.4	5063	40.3	4851	808	12
		Pooled test	ş	15	0.14	0.14	0.13	0.13			1727.8	4.39	326.5	317.0	0	321.8	5054	34.7	4848	39.2	12
		DOF applied	led				0.11	0.11							-						
6 Dec	108-112	Control	-32	5	0.42	0.30	0.42	0.33			1635.9	211	320.1	3114	0	3158	4355	20.6	4140	100	24
6 Dec	113-117	SCV	-32	2	0.23	0.33	0.17	0.35			1611.6	5.93	320.5	309.9	0	315.2	4066	55.0	3869	46.0	8
6 Dec	118-122	scv	-32	2	0.33	0.20	0.32	0.20			1615.0	6.11	320.6	308.7	0	3147	4115	47.0	3900	36.5	28
6 Dec	123-126	SCV	-32	4	0.45	0.36	0.35	0.32			1612.2	6.07	323.9	308.1	0	3160	4085	86.7	3872	71.4	2
7		Pooled test	st	14	0.34	0.30	0.28	0.29			1613.0	6.03	321.3	309.0	0	315.2	4089	629	3881	51.4	25
		DOF applied	ied				0.24	0.25				-									

Table 5 M865E3 pop rivet sequential rough handling test: summary of dispersion, velocity, and pressure data – 07 December

_											····		
Mean	74	tine	(SILL)		22	22	25	23	28	24	23	24	
ars)		vard	SD		30.7	23.7	23.9	65.3	71.0	28.8	35.2	46.6	Andrew Construction of the Park
ssure (b		Forward	Mean	-	4098	3843	3843	3856	3832	3817	3874	3844	
Chamber pressure (bars)		ar	SD	-	30.9	29.6	43.2	75.6	86.1	26.7	47.4	56.0	-
Cha		Rear	Mean		4372	4074	4054	4060	4046	4027	4089	4058	
1/8)		5	avg		318.0	318.1	318.1	317.9	318.2	318.5	317.6	318.1	
elocity (n		2000-	3000		0	0	0	0	0	0	0	0	
Mean falloff velocity (m/s)		-000	2500	**************************************	313.1	310.8	311.2	311.0	311.0	311.6	310.6	311.0	
Mea		-0	1000		323.0	325.5	325.1	324.8	325.4	325.4	324.6		
(sdw)			SD		2.83	4.29	4.33	6.78	7.51	4.34	5.38	5.59	
Muzzle (mps)			Mean		1638.0	1612.8	1612.4	1612.2	1612.7	1610.7	1615.6	1612.7	
	F	E	Ver										
cted	DOF	2500 m	Hor										
Boresight & wind corrected	, mils	E O	Ver		0.49	0.45	0.20	0.27	0.33	0.15	0.20	0.28	0.25
sight & w	<b>lispersior</b>	2500 m	Hor		0.29	0.26	0.21	0.55	0.42	0.16	0.21	0.33	0.29
Bore	Target impact dispersion, mils	1000 m	Ver		0.45	0,41	0.19	0.31	0.29	0.12	0.15	0.26	
	Targe	100	Hor		0.28	0.24	0.21	0.55	0.40	0.14	0.30	0.33	
			z		5	ß	S	S	rs.	5	5	30	
	Cond.	Temp	ပ္		-32	-35	-32	-32	-32	-32	-32	St	lied
		Round	type		Control	SHR	SHR	SHR	SHR	SRH	SRH	Pooled test	DOF applied
	est	round	unmper		129-133	134-138	139-143	144-148	149-153	154-158	159-163		
	Date	Fired	2001		7 Dec								

#### **DISTRIBUTION LIST**

Commander

Armament Research, Development and Engineering Center U.S. Army Tank-automotive and Armaments Command

ATTN: AMSTA-AR-WEL-TL (2)

AMSTA-AR-GCL

AMSTA-AR-CCH-B (5)

Picatinny Arsenal, NJ 07806-5000

Defense Technical Information Center (DTIC)

ATTN: Accessions Division (12) 8725 John J. Kingman Road, Ste 0944 Fort Belvoir, VA 22060-6218

Director

U.S. Army Materiel Systems Analysis Activity

ATTN: AMXSY-EI 392 Hopkins Road

Aberdeen Proving Ground, MD 21005-5071

Commander

Soldier and Biological/Chemical Command

ATTN: AMSSB-CII, Library

Aberdeen Proving Ground, MD 21010-5423

Director

U.S. Army Research Laboratory

ATTN: AMSRL-CI-LP, Technical Library

Blda. 4600

Aberdeen Proving Ground, MD 21005-5066

Chief

Benet Weapons Laboratory, CCAC Armament Research, Development and Engineering Center U.S. Army Tank-automotive and Armaments Command

ATTN: AMSTA-AR-CCB-TL Watervliet, NY 12189-5000

Director

U.S. Army TRADOC Analysis Center-WSMR

ATTN: ATRC-WSS-R

White Sands Missile Range, NM 88002

Commander
Naval Air Warfare Center Weapons Division
1 Administration Circle
ATTN: Code 473C1D, Carolyn Dettling (2)
China Lake, CA 93555-6001

Chemical Propulsion Information Agency ATTN: Accessions 10630 Little Patuxent Parkway, Suite 202 Columbia, MD 21044-3204

GIDEP Operations Center P.O. Box 8000 Corona, CA 91718-8000